

3.614

9 JAN 1918

Report to Chief Surveyors

7. 1. 18.

Received from Chief Surveyors

VESSEL'S NAME

s/s "Meiling"

Report Lon.

No 80482^a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement.)—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Screw shaft

When due

12. 16.

The 1st biennial survey of the screw shaft became due in 12. 16.

The Owners now state that it is not desired to retain the classification of this vessel.

It is submitted the class of the vessel be withdrawn from the Register Book & three dots inserted in lieu thereof indicating that the class has been withdrawn at the Owners request.

Withdraw class.
Insert . . .



© 2020

Lloyd's Register
Foundation

JIM

7/1/18

007021-007032-0064