

COPY.

THE CLARKSON THIMBLE TUBE BOILER CO.LTD.

613 Australia House,
Strand,
LONDON, W.C.2

10th March, 1938

Messrs. Abbott & Co.(Newark) Ltd.,
NEWARK ON TRENT.

Dear Sirs,

Contracts 617/618 - Crichton Vulcan
Contract 638 - Admiralty

With reference to Lloyd's Certificates issued in connexion with the above boilers, we have heard from Messrs. Crichton Vulcan that their two boilers are stamped by Lloyd's under numbers 585 and 586; certificates issued for the three contracts above are, however, as follows:-

584 & 586 - Crichton Vulcan,
585 - Admiralty.

It would therefore appear that you despatched Boiler No.584 to Finland instead of Boiler No.585.

We require new certificates for our clients, and have been in touch with Lloyd's Register, who suggest that the best thing to do is for you to get in touch with Mr. Kimber at Sheffield, explain the position to him, and obtain the new certificates.

Please do all you can to get this matter settled immediately, as Messrs. Crichton Vulcan are just on the point of handing over the ships and have asked for these certificates by Air Mail today.

Yours faithfully,

Lloyd's Register
Foundation

007072-007077-0053