

**COPY.**

# Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

BC

9th December, 1927.

Dear Sirs,

I am in receipt of Mr. Heck's letter of the 29th ultimo respecting the working pressure of the main boilers of the steamer "ROMA", No. 33340 in the Register Book, and on looking into the matter I find that the recorded working pressure of 200 lb. per sq. inch, as given in the Register Book, is an error. The approved working pressure of this vessel's boilers is 220 lb. per sq. inch, and on the completion of the vessel, the safety valves were reported by the Society's Surveyors at Genoa to have been adjusted to that pressure.

In the circumstances, the pressure will at once be corrected in the Society's Register Book to 220 lb., and the alteration will appear in the next supplement.

I am, Dear Sirs,

Yours faithfully,

Clerk to the  
Classification Committee.

The Surveyors,  
NEW YORK.



Lloyd's Register  
Foundation

007072-007077-0159