

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME NAPLES MARU Rpt. Kob. No. 109139¹¹⁶⁹⁹**The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey _____

The class is subject to indented plating etc. (p.s.a and s.s.f) being permanently repaired at the first convenient opportunity and to the windlass cylinder block being repaired at the next Annual Survey.


The greater part of the 2nd S.S. No. 2, due 5.40, has been held.

To complete the Survey the D.B. tanks require to be examined internally.

In reply to enquiry the KOBE Surveyors write, 5.41, the Owners are not in a position to say when the Survey will be completed.

The Year of Grace expired 5.41.

The case is submitted for the consideration of the Committee.



© 2020

Lloyd's Register
Foundation

13-11-41