

1

Sent to Chief Surveyors 10.10.24

Received from Chief Surveyors

13 OCT 1924

VESSEL'S NAME

s/s. "Argenfels"

Report

Lon

No. 88259<sup>a</sup>

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." — Extract from Sub-Committee's Report, 24/5/22.)

Nature of Survey

Boiler

When due

8.24.

The boiler survey became due in August last. no part has been held.

The Owners state that the vessel has been classed with the Germanischer Lloyd & request the class of this Society to be rephunged.

It is submitted the class of this vessel be withdrawn from the Register Book & three dots inserted in lieu thereof, indicating that the class has been withdrawn at the request of the Owners.

Withdraw class.

Insert ...

MSD  
10/10/24

MSD



© 2020

Lloyd's Register  
Foundation

007100-007115-0196