

POSTPONED SURVEYS.

Case of the S.S. "ESSO PANAMA"

No. 08820 in Reg. Bk. _____ tons, Built _____

Classed _____ Owners _____

Load Line Certificate expires Port of Registry 30.4.50.
Special Survey due 4.49. Repairs by 6.49.
Boiler Survey due 11.49.
Screwshaft Survey due 12.49.

Survey Due _____

In September last the Owners stated the vessel was laid up, and no decision had been reached regarding her future. Action was deferred accordingly.

In September last the Aruba Surveyor stated that according to local information the life expiry of this vessel would coincide with the 24 years survey.

In reply to enquiry the Owners now state that the position remains unchanged since their last communication.

Submitted a notation of "Laid up pending Survey" be recorded in the R.B.

Committee's Minute ~~WED 1 MAR 1950~~ *6 AM 28-2-50* *L.L.*

Decision FRI. 3 MAR 1950 *Laid up pending survey*

L.L.



© 2020

Lloyd's Register Foundation

For ~~98~~ Dept.
Please return to
"S" Dept.

0001 RAM E JMT



© 2020

Lloyd's Register
Foundation