

Will the Chief Engineer Surveyor kindly state when the
Screwshaft Survey is due in this case.

1921-12.7
P.M.S.
9-12-21



© 2021

Lloyd's Register
Foundation

007150-007160-0031