

Rpt. 8.

Received at London Office

No. 88201A

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Reg. Book. 68802 Survey held at on the Wood, Iron or Steel Sec. "EKSTRAND" Date, First Survey Last Survey

TONNAGE:- GROSS 2014 UNDER DEK 1646 NET 1245 Built at Donain, O. By whom American S.B. Co. When 1918

Owners A/S Strand & Managers C.B. Nielsen

Port belonging to Skien

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

WB=CellDBorDBa feet; uE&B feet; f feet; total capacity tons. FPT tons; APT tons; MT feet tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report, No. 13014 Port Rot

CHARACTER for Special Survey, Date of last Survey and of Periodical Surveys	Years Assumed - shape actual	Machinery and Boiler Surveys (including date of N.B., if any)
+ 100 A1	8-23	+ LMC 7-23
		CL-7-23
Sd Rot. No. 1-23		
Cargo hatches not fitted		

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? If so, by whom?

PAIRS, OR EXAMINATION AS PER RULE, FOR

STATEMENT OF DAMAGE REPAIRS :-	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

GENERAL CONDITION OF THE	State if Tanks have been examined inside	Dblig. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Felt.)
Age of Decks	State if Tanks now tested	Engine Room Skylights	When put on, Month Year
Days	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	Boats
Days	Ceiling	Scuppers	Masts, Yards, &c.
Days	& Fastenings	Cargo Hatchways	Condition, how ascertained (State if wedges removed)
Days	Cement or Asphalt (State which.)	Hatches	Sails
Days	Rudder	Planking of Wood Vessels	Equipment letter
Days	Steering gear and its connections	Caulking ditto	Anchors, No. of
Days	Windlass	Treenails ditto	Cables (State if now ranged)
Days	Have Pumps now been examined and found efficient?	Breasthooks & Stemson ditto	length size (on board)
Days	Have Sluice Valves now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Rule length size
Days	Have Watertight Doors now been examined and found efficient?	Timbers of Frame at openings ditto	Hawser & Warps
Days	Have Ventilators and their Coamings been examined and found efficient?	Ditto ditto at other places ditto	Standing & Running Rigging
Days	Bottom Plating	Stringers, Clamps & Shelves ditto	
Days		Salting ditto (State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,15," or "to remain as classed and to have record of survey, 1,15, and the notations of ss No. 1-15 and ptND15, &c."

Fee (per Section 29)	£	Fees applied for	19
Damage or Repair Fee (if any) per Sec. 29	£	Received by me	19
Printing Expenses (if chargeable)	£		
Surveyor's Fee (if any)	£		

Surveyor to Lloyd's Register of Shipping.

General Committee Thursday 6th November 1924 Classing for Lloyd's Register My decision confirmed

TUES. 4 NOV 1924

Character Assigned withdraw class + insert (....) Lewis Own

007161-007167-0173

Is Certificate required? If so, to be sent to