

1

12 FEB 1926

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Stl. Sc.K. "HOURTIN"

Report

Lon.

No. 88553

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey _____

When due _____

The 2nd.s.s.No.1 due 10,24 has been partly held.

The Bordeaux Surveyor now states he has been informed by the Owner that the vessel is now classed with the Bureau Veritas.

It is submitted the vessel's class be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at Owner's request.

Withdraw Class

Insert ...

11.2.25.



© 2021

Lloyd's Register
Foundation

007206 - 007218 - 0297