

AIR MAIL.

C O P Y.

LLOYD'S REGISTER OF SHIPPING.

Kakawa House,
Kakawa Street,
L a g o s,
9th October, 1947.

Dear Sir,

I am in receipt of your letter of the 23rd September, 1947, in connection with your stream trawler "LORD GAINSFORD" requesting information re surveys for Class Maintenance.

The procedure is as follows:-

Where a Surveyor to Lloyd's Register of Shipping is not stationed the local Lloyd's Agent (Sierra-Leone Coaling Co's Manager at Freetown) represents Lloyd's Register of Shipping.

You should apply to him when he will appoint a suitable technical person to carry out the surveys.

Our Rules call for the vessel to be submitted for Special Survey at four yearly intervals when the vessel is examined internally and externally on a slip or in dry-dock, the machinery is also to be examined in its entirety.

The screw shaft requires to be examined at three yearly intervals, the boiler once a year. The Surveyor makes recommendations for repairs as found necessary at these surveys and is responsible for seeing that his recommendations are carried out.

The above surveys could be carried out at Freetown or Dakar and as all surveys are due should be carried out as soon as possible.

Mr. Savage, the Sierra-Leone Coaling Co's Manager, as Lloyd's Agent will only be too glad to discuss the matter with you.

Trusting that this information meets with your requirements.

I am, Dear Sir,
Yours faithfully,

J. P. Holmen, Esq.,
Import & Export Merchant,
P. O. Box 130,
FREETOWN.

SURVEYOR.

Lloyd's Register
Foundation

007266-007275-0027