

Gms Rpt. No 8554.

It is submitted that the Hull Surveyors should be requested to state the dates on which the fitting the sea connections, stern bush & propeller were examined.

W. 21/1/13

W. 18/1/13

FR

© 2021

Lloyd's Register
Foundation

007276- 007287- 0279