

1

Sent to Chief Surveyors 2.2.26.

Received from Chief Surveyors 4 FEB 1926

VESSEL'S NAME SH. ss. - balm

Report Lon. No. 89241<sup>a</sup>

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required, and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/6/92.)

Nature of Survey 2<sup>nd</sup> S.S. No. 1 When due 1.26.

*Bl. due 1.26.*

The 2<sup>nd</sup> s.s. No.1 became due 1-26.

The Owners stated in July last that on expiration of the present classification certificates they did not propose to renew same.

It is submitted the class of the vessel be withdrawn from the Register Book and three dots (...) inserted in lieu indicating withdrawal of class at the Owners' request.

*Withdraw Class.  
Insert ...*

*[Handwritten signatures and initials]*  
3.2.26.



© 2021

Lloyd's Register Foundation