

COPY

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.3.

30th July, 1947.

Dear Sir,

Tanker "PANUCO"

S. I have to acknowledge receipt of your letter of the 3rd ultimo enclosing reports of survey held in April/May 1947 by a Surveyor appointed by Lloyd's Agents at Tampico.

The case has received the consideration of the Committee and notation of "Examined 5,47" valid for a period of 12 months has been assigned together with notation of "LMC 5,47".

With regard thereto, I think it well to point out that this vessel requires 300 fathoms of chain cable, and when the cable was last ranged (April 1946) 255 fathoms were on board. In his report, however, the Surveyor states that there are 720 feet of cable on board, and it is concluded that this length refers to one side only. I shall be glad if you will communicate with Lloyd's Agents at Tampico and ascertain if this is so, and also the total length of cable on board.

Yours faithfully,

Clerk to the
Classification Committee.

Wm. Bennett, Esq.,

NEW YORK.



© 2021

Lloyd's Register
Foundation