

2

Sent to Chief Surveyors

Received from Chief Surveyors

22 APR 1942

VESSEL'S NAME

MAUI

Report

S. Fo.

No. 8499

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

2ND No. 3

SURVEY ~~PARTLY HELD~~ COMMENCED, DAMAGE & ALTERATIONS.

When due 10.41

When proposed to be completed

Portion of Survey held, &c.

Peak and deep tanks, and No.s 2 & 4 D.B. tanks tested.
Cofferdam in boiler room and windlass examined.

Subject to sternframe E.W, 11.40 being specially examined at the next dry docking, and to a tower anchor and 30 fathoms of chain cable being supplied at the earliest opportunity.

Insert in R.B.


Platform deck in No.2 hold

(DOCKING DATE)
(12.41)

S.S. PART HELD.

8.6. n.yk.
1-5-42

The Surveyors should be requested to forward a copy of the plan of New Platform Deck approved in the New York Office 25.11.41, for records in this office.



© 2021

Lloyd's Register
Foundation

007439-007445-0255