

COPY.

E.

LLOYD'S REGISTER

NAGASAKI.

22nd August, 1934.

The Secretary,
LONDON.

Dear Sir,

Mitsubishi Engine No. 555 and 556
Nagasaki Reports Nos. 1976 and 1983.

--

I beg to state that an error has been made in reporting the weights of the flywheels of above mentioned engines. These weights should have been 8033 kg. for engine No. 555 and 8050 kg. for engine No. 556 instead of 7645 kg. as reported for both cases. I may add that these are the actual weights of the flywheels as fitted.

(s)....

H.D. Buchanan.

Surveyor.



© 2020

Lloyd's Register
Foundation

007465-007473-0200

2011

© 2020

1139

 $\bar{n}_c, 12, 30.$

the pens

160

Whi
lerstood
my rep
iety, or

the

all Se

Weng

Ms. 10014