

2m,7.44.

6 OCT 1945

to Chief Surveyors.....

Received from Chief Surveyors.....

SEL'S NAME "REHEARO" REPORT Lon. No. 112977A

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

of Survey..... When due.....

The Owner has decided not to renew the class
of this trawler.

IT IS SUBMITTED the class of this trawler be
withdrawn from the Register Book and three dots (...) inserted
in lieu indicating withdrawal of class at the Owners' request.

Withdraw Class

Insert (...)

28.9.45



© 2020

Lloyd's Register
Foundation

007506-007517 - 0163