

UNCLASSIFIED SECTION 435

(Received at London Office)

No. 11753A

Rpt. 8

# REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report... 19... When handed in at Local Office... 19... Port of...  
No. in Survey held at... Date, First Survey... Last Survey...  
Reg. Book... (No. of Visits...)

01428 on the Wood, Iron or Steel M.S. "ANNE LOUISE"  
Built at Quebec, P.Q. By whom G. T. Dauce & Sons Ltd When 1946 - 11  
GROSS 491 Owners Dampskibsselsk Phønix A/S Owners' Address  
UNDER DK 481 Managers Harris Andersen Port belonging to Esbjerg.  
NET 221

Surveyed Afloat or in Dry Dock? Name of Dock... Destined Voyage...  
Cell DBa... feet; uE & B... feet; f... feet  
total capacity... tons. FPT... tons; APT... tons; MT... feet... tons.

Only alterations in the existing records of tanks should be inserted.  
N.B.—All alterations in the existing records should be underlined.

Last Report, No. 117520 Port Lon

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Was a damage report made by anyone else? if so, by whom?

### Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER * for Special Survey Date of last Survey and of Periodical Surveys	Machinery and Boiler Surveys (Including date of N.B., if any).
100A1	LHC 11,46
with freeboard	LHC(M) 1,49
11,48	DBS 1,49
st elec welded	Emach 43 fitted 146
WDB	TS 11,48 (DG)

For service in the Black Sea, Turkish North West African Coastings but north of lat. 60°N including Iceland, limited to summer months Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.

Oil Engines.

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items :-
Renewed ...								
Removed and Faired or Repaired								
Faired or Repaired in place ...								

### PRESENT CONDITION OF THE

Decks	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.) When fitted, Month Year
Caulking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	Boats
Coamings	Cement or Asphalt	Oil Bunkers	Masts, Yards, &c.
Beams & Fastenings	Rudder	Scuppers	Condition, how ascertained (State if wedges removed.)
Outside Plating	Steering gear and its connections	Cargo Hatchways	Equipment letter
" " In way of sidelights	Windlass	Hatches	Anchors, No. of
Frames	Have pumps been examined and found efficient?	Planking	Cables (State if now ranged)
Reverse Frames	Have Sluice Valves been examined and found efficient?	Caulking	" length mean diamr. (on board.)
Longitudinals	Have Watertight Doors been examined and found efficient?	Treenails	" Rule length size
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	Chain Locker
Decks	Have the Tanks been examined internally?	Transoms, Pointers & Crutches	Hawsers & Warps
Beams	Have the Tanks been tested?	Timbers of Frame at openings	Standing and Running Rigging
Inner Bottom Plating		" " at other places	Sails
Double Bottom Plating	Air and Sounding Pipes	Stringers, Clamps & Shelves	
Double Bottom Plating	Doubling Plates under Sounding Pipes	Salting	
		State if examined.	

### General Observations, Opinion as to Class, Recommendation, &c. :-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of as No. 1-38."

Survey Fee (per Section 29)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 29)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute... FEB 10 1950  
Character Assigned... withdraw class & insert (...)

Surveyor to Lloyd's Register of Shipping

Special General Committee  
Thursday, 23<sup>rd</sup> March, 1950.  
Committee's decision  
Lloyd's Register  
confirmed P/B