

COPY

Lloyd's Register of Shipping

NOV 1933

MEIKAI BUILDING

32, AKASHI-MACHI,

KOBE.

16th February 1933.

RT. No. 1557.

THIS IS TO CERTIFY that at the request of

Mitsubishi Zosen Kaisha, Nagasaki,

open hearth mild steel Boiler quality Plates made to the order of

Mitsubishi Zosen Kaisha, Nagasaki,

intended for Yard No. 532, were inspected and tested at their

works on dates as stated below.

Samples taken from this material were subjected to the tensile, and bend tests prescribed by

Rules of this Society for Boiler material with satisfactory results.

For identification of material see signed invoice attached hereto. No. 6288.

RESULTS OF TESTS

Item No.	Test No.	Charge Mark.	Thickness.	Breadth	Area	Total Tons.	Tons per square inch	Extension in 8 ins. %	Bend.
<u>FLANGING QUALITY</u>									
32	1	D4369AIII-2921	.64	1.95	1.248	34.134	27.35	27.5	Good
			.64	1.97	1.261	34.004	26.97	29.0	"
			.80	1.47	1.176	31.277	26.59	29.0	"
3	D4227A	"	.80	1.46	1.168	31.254	26.76	28.0	"
2	8	D4370B	.75	1.96	1.470	38.871	26.44	29.5	"
			.51	1.96	1.000	29.442	29.44	28.0	"
	9	D4441BIII-2919	.51	1.96	1.000	29.442	29.44	28.0	"
<u>SHELL QUALITY:-</u>									
	2	D 75B III-3071	.48	2.00	.960	29.170	30.39	28.0	"
	5	D7432C I-5179	.59	2.00	1.180	37.281	31.59	22.0	"
	10	D7737A II-5787	.48	1.99	.955	28.746	30.10	23.5	"
	10	D4582B II-5990	.49	1.96	.960	28.808	30.01	24.0	"
			.99	1.48	1.465	46.865	31.99	23.0	"
32	11	D5171B II-5756	.99	1.48	1.465	46.734	31.90	23.0	"
33	12	D74B III-3071	.78	1.50	1.170	35.500	30.34	23.0	"

- THE END -

13 Pieces.
4.258 Kgs.

Yen

expenses

To be used for Donkey Boilers

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register, Book or other publication of the Society or for any error of judgment, fault, or negligence of the Surveyors, other Officers or Agents of the Society."

009553-009562-0300