

F.E.

Received by Chief Ship Surveyor 24. 1. 08

Received from Chief Ship Surveyor _____

VESSEL'S NAME St. Steam Trawler "Piken" Rpt. Hull No. 19758

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

| Items. | Additions (if any) required by Rules, or as approved. | On account of:— |
|--|---|----------------------|
| Main Sheerstrake . . | <u>8/16" in lieu of 7/20"</u> | <u>Not required.</u> |
| Spar Sheerstrake . . | <u>"</u> | <u>"</u> |
| Description of Framing:— <u>Ordinary, increased to compensate for omission of reverse frames.</u> (viz., ordinary, deep, zed, channel or bulb-angle). | | |

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed \pm 100A1 ("Steel") "Steam Trawler" as recommended.

\pm 100A1 ("Steel") "Steam Trawler"

1DR.

BK 7½" 4BH Cem. Length 100' 467' F20'



24/1/08
2020

Lloyd's Register
Foundation