

Steel Steam Trawler "EVELYN", No. 57542 in Register Book.

It is submitted the Owners should be informed that in order to render this vessel eligible for re-classification in the Society's Register Book it will be necessary for the full requirements of the second Special Survey No. 3, including drilling, to be carried out, and the vessel placed in thoroughly good and efficient condition to the Society's satisfaction.

No Report has yet been received from the Society's Surveyors at Hull of any examination having been made by them on this vessel, as referred to in the third paragraph of their letter, but enquiry might be made of the Surveyors on the subject.

At the same time the Owners should be informed that in accordance with the Committee's usual practice it would not be possible to reinsert the vessel's original classification until the Special Survey above referred to had been completed.

26. 5. 31.



© 2020

Lloyd's Register
Foundation

007572-007589-0206