

1

Sent to Chief Surveyors

Sunbank
Yn.

Received from Chief Surveyors

30 MAR 1928

VESSEL'S NAME Stl. Sc. "DAISHU MARU".

Report Lon.

No. 92480a.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

The class is subject to the outer plates, repaired by O.A. welding 4.27, being specially examined at the next dry docking.

The Kobe Surveyors now state the vessel has recently been purchased by Japanese Owners who have informed them that they do not desire to continue the classification in this Society's Register Book.

It is submitted the class of the vessel be withdrawn from the Register Book and three dots (...) inserted in lieu, indicating withdrawal of class at the Owners' request.

Withdraw class
Insert ...

29. 3. 28.



© 2020

Lloyd's Register
Foundation