

s/s "Sunbank."

It is submitted the Leith Surveyors should be requested to return the report of the donkey boiler of this vessel, as this does not appear to have been received at this office.

W.D.
13/11/19.

Lloyd's Register
Foundation

007668-007678-0169