

COPY.

Lloyd's Register of Shipping.

71, Fenchurch Street, E.C.3.

2nd February, 1937.

Dear Sirs,

S. With reference to the classification in the Society's Register Book of your motorship "HOYO MARU", I beg to acquaint you that a report has come to hand from the Society's Surveyors at Yokohama, from which it appears that the starboard Donkey Boiler has been examined on account of damage stated to have been sustained through shortage of water.

The Surveyors report that both furnaces had collapsed and the tube plates were affected, and in the circumstances the vessel's class has been continued in the Register Book subject to this boiler not being used again until it has been repaired and satisfactorily reported upon by the Society's Surveyors.

I am, Dear Sirs,

Yours faithfully,

Clerk to the
Classification Committee.

Messrs. Nippon Kabushiki Kaisha,
6, Marunouchi, 3-chome,
Kojimachi-ku,
TOKIO, Japan.



Lloyd's Register
Foundation

007679-007687-0100