

273 COPY  
LLOYD'S REGISTER OF SHIPPING,

Yokohama, 17th February, 1930.

This is to Certify that at the request


of Messrs, Unosawagumi Tekkosho, attend at their works, at  
Shibuya, Tokyo-fu, on the 6th February 1930, for the purpose  
of testing the under mentioned pumps made to the order of  
Messrs, Mitsubishi Zosen Kaisha, Ltd., Nagasaki, for their  
Ship No.474.

2 sets of 90 mm x 60 mm x 100 mm Worthington type  
donkey boiler feed pumps, Nos. 2085-G and 2085-H.

The steam cylinders, valve chests and their  
fittings were tested under hydraulic pressure of 14 kgs/cm<sup>2</sup>  
with satisfactory results.

The pump barrels, valve boxes and their fittings  
were tested under hydraulic pressure of 15 kgs/cm<sup>2</sup> with  
satisfactory results.

For identification purpose these pumps have been  
marked as under:-



*J. Michalos*  
Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-  
While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be  
understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any in-  
accuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication  
of the Society or for any error of judgment, default, or negligence of the Surveyors, other Officers or Agents of the Society."

21 1930

© 2020  
Lloyd's Register  
Foundation

007679-007687-0204



1930

Society or for any error of judgment, default, or negligence of the Surveyors, other Officers or Agents of the Society".

In any report or certificate issued by the Society or its Surveyors or in any entry in the Registered Book or other publication made by the Committee nor the Society are under any circumstances whatsoever to be held responsible for any, in so far as the Committee use their best endeavours to ensure that the functions of the Society are properly executed. It is to be noted that the Committee are not responsible for any error or omission in the Registered Book or other publication.

While the Committee are not responsible for any error or omission in the Registered Book or other publication, it is to be noted that the Committee are not responsible for any error or omission in the Registered Book or other publication.

Certificate is issued upon the terms of the Rules and Regulations of the Society which provide that:—

Emphor to Job, & Mediator

Lloyd's Register  
Foundation

6/5/30 J. E. H.

三〇

100

number as noted:-

need even have been identified during these "studies."

mele, foreste, lagos, vauqueiros e de 10 mil/ha, 400

the drain pipe, the valve was and the fittings

Library of Congress

filings were tested under hydrostatic pressure of 14 ksc/cm<sup>2</sup>

rielt den studio of Law, established in 1880.

General Butler Red Bombs, Nos. 5082-G and 5082-T.

3 sets of 30 mm x 60 mm x 100 mm Morphington type

10.434.

Wesleyan Methodist Book Concern, Ltd., Managers, for their

on February 1, the undermentioned jumps made to the order of

Ships, 1000-10, on the 6th February 1880, for the purpose

Members, Unobscured by Taxation, attend at their works, at

And is to certify that at the request

1992

Yokohama.

From James Munroe & Co. 19.

TOYD, S REGISTER OF SHIPPING

СОБА

**STEEL WORKS**

Telephone No. 11 AIRDRIE.

“CALDERBANK.”