

Lloyd's Register of Shipping,

(MEIKAI BUILDING)

32, AKASHI-MACHI,

KOBE, 30th. November 1929.

No. 2260.

This is to Certify that at the request

Messrs. The Kobe Steel Works Ltd., Kobe.

Open Hearth Steel Forgings or Castings named below ^{was}/_{were} examined and
at their works on 12th. Sept. to 21st. Nov. 1929 (4 visits)

found to be as far as could be ascertained, sound and free from defect.

(4) Connecting Rods for Air Compressor of Emergency Air

Compressor with Hot Bulb Engine S.P.C. No.6.

examined in finished condition.

| Test Mark | Tenacity Tons/sq in | Elongation % in 2" | Bend 1" x 1/2" x 180° |
|-----------|------------------------|-----------------------|--------------------------|
| B3145B2 A | 32.5 | 31 | Good. |
| " B | " | " | " |
| " C | " | " | " |
| " D | " | " | " |

Connecting Rods are intended for Mitsubishi Zosen Kaisha

Ship Nos. 471 to 474

and ^{has}/_{have} been stamped as follows:-

TEST MARKS B3145B2-A-B-C-D.

LLOYDS

No. 2260

21-11-29

A.W.L.R.

Yen 28.00

1.00

Awatt

Surveyor to Lloyd's Register.

ificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-
the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be
at neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy
or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the
any error of judgment, default, or negligence of the Surveyors, other Officers or Agents of the Society."



Lloyd's Register
Foundation

007679-007687-0214