

Lloyd's Register of Shipping.

NEW ZEALAND CHAMBERS.

483 COLLINS STREET.

Melbourne, 9th April 1936

LLOYD'S REGISTER
RECEIVED
18 MAY 1936

LONDON

Secretary,

L O N D O N.

Sir,

S.S. "YARRA"

With reference to your letter dated 30th September the freeboards assigned to this vessel have now been marked on the ship's sides and the conditions attached to the assignment have been complied with as follows:-

The coamings of Nos. 1, 2, 4 and 5 hatchways have been reinforced by horizontal 8" x 3½" bulb angle stiffeners to which brackets have been attached.

The hatchway fore and afters have been examined and found to be closely and efficiently in their sockets.

The freeboard certificate and copy enclosed with your letter have been issued and the Sydney Surveyors advised accordingly.

Report of Verification is enclosed herewith.

I am, Dear Sir,

Yours faithfully,

B. P. Fielden.



© 2021

Lloyd's Register
Foundation

Referred to the Chief Ship Surveyor.
(Freeboard).

18 MAY 1936

*Particulars noted on report
Books examined.*

E

*date
19/5/36*



© 2021
Lloyd's Register
Foundation