

007707-007713-0146

2E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME

Lanais.

Rpt.

Per

No.

4919

of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

~~COMPLETION OF~~ SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No. 2

This Survey, due ^{now} 4:39 ~~partly~~ held at

~~completed~~, and the following repairs carried out (due to

An electric light plant installed.
This installation is not in all respects in conformity with the Rules.

It is submitted the vessel is eligible to remain as classed, with notation of ~~these~~ 8:39 as recommended.

Subject to the electric light installation being placed in ~~about~~ conformity with the Rules. It is concluded that the Condenser was examined but the should be confirmed. As to the electrical installation the Surveyor should state what is the statement that so far as practicable it is in conformity with the Rules. They should forward another report on the installation giving the particulars omitted from the present report of main cables, the currents carried by each circuit of the Electrical Engineers, whether the conduits all respects in conformity with sec 6 (a) (c) of the Rules protection other than armour is given to the wireless circuit as to the Rules. They should send the plans of the installation, required by Rule.

DA 7/9/39