

as per Rule		Feet.	Inches.	BREADTH—		DEPTH, ACTUAL—Top of Floors to top of Upper Dk. Beams						24	0 1/2	No		
as per Rule		380	6	Moulded		53	0	Do.		do.	do.	do.	Second Dk. Beams	14	7	No

CABLEGRAMS: NYMDIBLE, NEW YORK

TELEPHONES { 220 } WHITEHALL
 { 221 }
 { 222 }

LLOYD'S REGISTER OF SHIPPING
17 BATTERY PLACE

LLOYD'S REGISTER
LONDON.
RECEIVED DEC 4 1920
ANSO

Dear Mr. Mayne,

With reference to your letter of the 27th ultimo
and to Seattle Report No. 992 on the Steamer "RED HOOK"
I attach hereto a letter dated 16th instant received from
the Surveyors from which it will be seen that a record
of "pt.cem" should be made in this case.

Yours faithfully,

R. A. Mayne

F. A. Mayne, Esq.,
London.

RPH/RT



© 2020

Lloyd's Register
Foundation

007714-007721-0348

Tee Bulb, or Channel.....
Angles on upper edge.....

Forecastle Deck Stringer Plate, b'dth & th'kns
,, Angle on ditto.....

See Minutes of

For Mr. Mague

Jan. 4. 12. 20

-4 DEC 1920

Recd pt. Ceni

M
9.12.20

[Handwritten signature]

[Handwritten signature]

[Faint handwritten text]

[Faint handwritten text]

[Faint handwritten text]

[Faint handwritten text]

[Faint handwritten text]

[Faint handwritten text]

[Faint handwritten text]

[Faint handwritten text]

[Faint handwritten text]

[Faint handwritten text]

[Faint handwritten text]

[Faint handwritten text]

[Faint handwritten text]

[Faint handwritten text]

[Faint handwritten text]

[Faint handwritten text]

[Faint handwritten text]

[Faint handwritten text]

[Faint handwritten text]

[Faint handwritten text]

[Faint handwritten text]

[Faint handwritten text]

[Faint handwritten text]

[Faint handwritten text]



© 2020

Lloyd's Register
Foundation