

AMERICAN BUREAU OF SHIPPING

Date June 30, 1919.

PORT No. 1489		Report on Castings or Forgings INTENDED FOR				PORT OF Seattle	
SSEL 33-34		SHIPBUILDER Todd Dry Dock & Construction Co.				SHIPYARD HULL No.	
TAMPED A.B. 72 No. See below		ENGINE BUILDER GMDV				WORKS ENGINE No.	
		OWNER U.S.S.B., Emergency Fleet Corporation				OWNER'S CONTRACT No.	
		PURCHASER Todd Dry Dock & Construction Co.				PURCHASER'S ORDER No. 01358	
ACCEPTED (Date) 6-27-19 6-13-19		MANUFACTURED BY Pacific Construction & Engineering Co.				MANUFACTURER'S No. 247	
SHIPPED (Date)		FOR (State Structure) Engine Construction				WEIGHT	
INVOICE No.		PROCESS OF MANUFACTURE Open Hearth Steel Forgings				ANNEALED Yes	
DESCRIPTION	PIECE NUMBER	HEAT NUMBER	TEST PIECE AREA	TENSILE		% ELONG. in 2	REMARKS BENDS, ETC.
				BEAM	PER SQ. IN.		
3 Cr. Shaft Pins	259-Z	3358	.250	16590	66360	31.0%	Fracture Bend Cup silky O.K.
3 Crank Pins	263-A	5596	.250	15660	62640	30.5%	Ang. " O.K.
3 Cr. Shaft Pins	263-B	1718	.250	15650	62600	32.5%	Irreg. " O.K.
1 Crank Pin	263-C	506	.250	19900	79600	27.5%	1/2 Cup " O.K.
C.S. Pins 3 C.S. Pins	263-D	1718	.250	15620	62480	34.0%	1/2 " " O.K.
" " 1 " "	263-E	5596	.250	15320	61280	31.5	Irreg. " O.K.
Particulars of Drop Testing, Slings and Hammering							
1st Visit 6-11-19 Last Visit 6-27-19 No. of Visits 2 Fees Expenses TOTAL		<p>I have to report that the above mentioned Forgings have been tested by me in accordance with the requirements of the Rules as noted.</p> <p>Signed <u>L.T. Holt.</u> SURVEYOR</p> <p>CHIEF SURVEYOR</p>					

© 2020

Lloyd's Register
Foundation

007714-007721-0353