

15c, 9, 41.

POSTPONED SURVEYS.

Case of the Steamer "OSMUSSAAR".

No. 79991 in Reg. Bk. 2229 - 1324 tons, Built 1909 4 mo.

Classed ~~LOCAL~~ LMC MS 2,37 Owners A/S Merilaid & Co.

5,40

BS 7,40

s.s. Lth. 2nd No. 3-6, 33 TS CL 5,40

s.s. Tln. No. 1 - 37

Port of Registry Tallinn

NO LATER SURVEY REPORTED

see below

Surveys Due 3rd Special Survey No. 2 due 6, 41: Boiler Survey due 7, 41.

This vessel formerly flew the Estonian Flag, but in August 1941, as she was reported to be at Murmansk, and presumably under the control of the U.S.S.R., a notation of "No later survey reported" was assigned. In February last she came under survey at Halifax, N.S. on account of damage, and it was recommended that permanent repairs should be effected on the vessel's arrival at New York.

The following letter has now come to hand from the New York Surveyors:-

" The Baltimore Surveyors advise that the steamer "OSMUSSAAR" is under repair at that port and that the American Bureau Surveyors are in attendance.

The Surveyors pointed out to the Master that the vessel was classed with this Society, but he stated that Lloyd's classification was no longer desired. The matter was also referred to a representative of the Amtorg Trading Company at New York who concurred in the Captain's statement."

According to Lloyd's Index the vessel is now under the Russian Flag and owned by Sovtorgflot. The case is submitted for the consideration of the Committee.

Committee's Minute **FRI. 21 MAY 1943**

19.5-43

Decision

Special General Committee
Thursday 17th June 1943
Classing Committee's decision confirmed

007746-007753-0111

© 2020

Lloyd's Register
FoundationRegis
as clas