

Time of Receipt 12.25-

TELEGRAM.

LLOYD'S REGISTER,
LONDON.

RECD 29 SEP 1918

442

ANSP OFFICE



TELEGRAPHS.

Office Stamp

Office of Origin and Service Instructions

Words Charges to pay

Middlesex T

14



THIS FORM MUST ACCOMPANY ANY ENQUIRY RESPECTING THIS TELEGRAM

Committee
Gen. Sec.

11.3A

Colony 31768 Please forward
breachboard Certificate
mention follows
Surveyors

Indian Summer Line " "

Winter Line below " "

Winter North Atlantic Line " " "

17.9.18



© 2021

Lloyd's Register
Foundation

If the frames, skin planking, or ceiling are of unusual thickness the breadth of vessel to inside of ceiling should be reported if possible.
In vessels obtaining an allowance for deck erections under Para. 11 where the sheer drops abaft amidships the height of the B.Q.D. is to be taken from the level of the top of the amidship beam.
In flush-decked vessels the total standard mean sheer means the sheer measured at the stem and stern-post. In vessels having poops and forecastles, it means the sheer measured at points distant

State
The Surveyor shows
line of keel
survey

Referred to the Chief Ship Surveyor.

SEP 29 1915

J. H. Wood

to Mr. C.

*Forward cents to Mr. C.
N.Y. 29.9.19*

TELETYPE



© 2021

Lloyd's Register
Foundation

of
In this
In this
pos
+
In
sals
pos
of
Correspo
(Para
FREEE
Pa
i
Sta
Pre
Is
Ins
Cent
2m.6.1
V
d
in
by
sta
able
Na