

Received by Chief Ship Surveyor 5. 10. 08

Received from Chief Ship Surveyor

VESSEL'S NAME *Thorn S.S. Tug "Consort"* Rpt. *Kull* No. *20574*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Just entry

It is submitted that before this case received the consideration of the Committee, the London Surveyors should be informed that this Tug has been towed ~~to~~ Yarmouth for the fitting of her machinery, and to complete the survey for classification, the engine and boiler casings require to be refitted and riveted after the machinery has been fitted on board. They should be requested to give the case the necessary attention, and on completion of the work to their satisfaction, to report upon the same on Form No.8 for the information of the Committee, with a view to the classification of the vessel.

*Lr Ldn Surs 6. 10. 08**C.A.P.
6/10/08*

© 2021

Lloyd's Register
Foundation

007754-007761-0092