

DISCLOSED
SECTION.

No. 392

13th July, 1948.

Dear Sir,

I have to acquaint you that in view of the information received from the New Orleans Surveyor to the effect that the steamer "AMERICAN FISHER" is being repaired afloat under the supervision of the American Bureau Surveyor and our services have not been requested, the Committee have now given instructions for this vessel's class to be expunged from the Register Book with a Red Line.

Yours faithfully,

Clerk to the
Classification Committee.

The Principal Surveyor,

NEW YORK.



© 2021

Lloyd's Register
Foundation

00 7881-007 887. 0173