

COPY. (SEE SFO. REPORT NO. 7722.)

Lloyd's Register of Shipping.



Port SAN FRANCISCO

AUGUST 20th, 1937.

This is to Certify that I have

Surveyed the S. S. "AMERICAN FISHER" of San Francisco, 4779
tons gross register, while lying afloat and on drydock at this
Port for damage due to explosion and fire, May 24th, 1937, also
part Special Survey 2nd No. 3.

and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report, stating that all repairs
recommended by me have been completed to my satisfaction, and
that I have **Recommended** that she be continued as now classed
with fresh record 8-37 and notation of S.S. S.Fo. 2nd No. 3-8, 37
when survey is complete. **Fish Reduction Ship (Not to carry
Petroleum in bulk) (Damage repairs now complete.)**
being fit to carry fish meal and fish oil only.

(Signed) F. G. Archbold

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."