

1

Rec'd
Sent to Chief Surveyors 30. 11. 36

Received from Chief Surveyors

VESSEL'S NAME Sh Lc "AMERICAN FISHER" Report S. To No. 7612For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required at 1 to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Alterations When due

Subject to stern frame repaired by (E.W. 7.35) being specially
examined at next dry docking.

NAB Yato
2-12-36

Delete "Carrying Petroleum in Bulk"
Insert "Fish Reduction Ship"
Amend 13 BH (8 to U.D. 5 to 2nd db)
to 8 BH

007881 - 007887 - 0209