

SS Yankee Arrow.

It is submitted the Philadelphia Surveyors
be requested to state the pressure to which
the steel steam pipes have been tested &
to describe the insulation of the electric light
cables as these items have been omitted
from the report.

Recd
2/9/81

© 2020

Lloyd's Register
Foundation

007909-007918-0314