

and subsequent repairs... other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. When replacement of Anchors or Chains is reported the particulars should be clearly stated in the form shown below. State also the dates and initials of any letters respecting this case.

In dan

Received from Chief Surveyors.....

Chief Surveyors.....

L'S. NAME

Tug "EMPIRE CHARLES"

REPORT

Lon.

No. 115264A

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." (Extract from Sub-Committee's Report, 24/5/92.)

When due.....


Survey.....

A letter dated 22nd September 1947 from the Admiralty states that the classification of this vessel may be withdrawn, as she is now permanently allocated to Dockyard service, and no further arrangements for Annual Survey under the Rules of this Society will be required.

It is accordingly submitted the class of this vessel be withdrawn from the Register Book, and three dots with date underneath be inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw Class

and insert (....)
9,47



Lloyd's Register
Foundation

007919-007929-0287

efficient?

Transoms, Pointers & Crutches

Timbers of Frame at openings