

Sanitary discharges, each with its own discharge pipe.  
The lowest sanitary discharge being 3'-4" below the board keel. ✓

Rpt. 9a.

Port of

Morani

Continuation of Report No.

~~dated~~

32684

on the

See Form C 11(d) Sydney. dated 25/3/36.

A new hatch coaming erected within the after deck house on the forward starboard side for access to the after hold. Size of opening

3'-4" x 2'-5½", 9" x 3 x .37 B.A coaming

2½" ribs, 2½" wood covers with cleats, battens & tanpaulin.



© 2020

Lloyd's Register  
Foundation

007458-007466-0103

Length of Bulwark

Height of Bulwark

Size of Freeing Ports

Number each side

Area each side

Rule area each side