

Received by Chief Ship Surveyor 24.2.17Received from Chief Ship Surveyor 2 MAR 1917VESSEL'S NAME Steel S. S. Coreya Rpt. Ln No. 79414

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey DAMAGE.Damage through stranding

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed	3	26					
Removed and faired or repaired.....	34	29		17	6		
Faired or repaired in place.....	6	12			2		

Other items:-

Vessel examined in dry dock. Bottom coated.
 Stern frame faired in place.
 2 bower anchors 1 kedge & 90 fathoms of cable
 of proper weight and test supplied.

It is submitted the vessel is worthy to remain as classed with
 record of Survey 2.17 as recommended

100-A.1.
 Steam trailer
 2.17 Ln



© 2020

at.
 7.3.17
 Lloyd's Register
 Foundation