

1E

ed by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

EL'S NAME

Munialto

Rpt.

Hel.
Hel.

No.

52201
18443

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine

Triple Expansion

If Boilers fitted with forced draught

Tail Shaft. If fitted with a continuous liner

If fitted with an outside gland of }
approved type

Yes
*No**Yes*

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, ^{& Admiralty specifications} and it is submitted she is eligible to be classed *+ LMC 10.43.*

L.H.
12/11/43.

© 2021

Lloyd's Register
Foundation

007967-007976-0246

State the principal additional spare gear supplied

see attached list.