

COPY

X
TELEGRAM from New York 25/10/47

COMMITTEE LONDON.

"RUBERCABLE MOBILE REPORT 2296 KATHRYN SUMMER FREEBOARD
ASSIGNED BY AMERICAN BUREAU TWELVE FEET FIVE SEVENEIGHTHS
INCHES REPORTS C11 AND C11 COMP BEING FORWARDED STOP COPIAPO
AND ACONCAGUA SUMMER FREEBOARD ASSIGNED BY AMERICAN BUREAU
FOURTEEN FEET NINE THREEQUARTERS STOP BEATRICE SUMMER
FREEBOARD ASSIGNED BY AMERICAN BUREAU TWELVE FEET FIVE
SEVENEIGHTHS STOP IT IS AGREED THAT CLASS IN ALL CASES SHOULD
BE WITH FREEBOARD" NYMDIBLE



© 2020

Lloyd's Register
Foundation

007997-007980-0114

are in excess of rule requirements but the chain cables are deficient
in diameter by $\frac{1}{16}$ ". The equipment should be in accordance with the