

6c.10.37.

1E

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor
Hul. No. *51373*
Rpt. *Y.S.* No. *64226*
" " *64105*

VESSEL'S NAME *Empire Willow*

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(*The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Type of Engine *Triple Expansion.*

If Boilers fitted with forced draught

Yes

Tail Shaft. If fitted with a continuous liner

No

If fitted with an outside gland of approved type

Yes

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, ^{M.O.S. specification} and it is submitted she is eligible to be classed *+ LMC 10.41.*

The Hul. Surveyors should be requested to furnish particulars of the independent feed & bilge pumps (and ballast pump if any) as these have been omitted from the report.

This also applies to the sister vessel Empire Maple.

See LH. 18/11/41.



© 2020

Lloyd's Register Foundation

007488-007997-0068

see also attached to Glasgow Rpt.