

Received by Chief Ship Surveyor

5/12/10

Received from Chief Ship Surveyor

VESSEL'S NAME

Sd Motor Lighter 'Cornelis' Rpt. Am No. #684

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

First entry

It is submitted that before this case reaches the consideration of the Committee, the Amsterdam Surveyor should be requested by wire to state whether the tank by putting '30 as reported or '33 as required ~~then~~ intermediate revenue frames are not fitted.

Tel. 2.5717/10

M

RBA

5/12/10



© 2020

Lloyd's Register
Foundation

007488-007497-0193