

COPY.

Lloyd's Register of British & Foreign Shipping

71, Fenchurch Street, E.C.

ENCLOSURE

15th December, 1910.

Sir,

With reference to your report No.4684(b) on the Electric Lighting Installation on board the Motor Lighter "CORNELIS", I have to request that you will state whether the number and sizes of the electric lighting cables as given on the report are correct as they do not appear to agree with the areas given. I have also to point out that the area of the cables should equal one square inch per 1000 amperes.

The report referred to is returned herewith.

I am, Sir,

Your obedient Servant,

Secretary.

J.B.Slebe, Esq.,

AMSTERDAM.



© 2020

Lloyd's Register
Foundation

007988-007997-0198