

For the information of Surveyors and the Committee only.

Received at _____ Office, _____ 19

Lloyd's Register of Shipping.

(Report on Machinery, No. 3488)

Port Skun

6079

ENGINE FORGINGS ~~CRANK SHAFTS~~

I have to report that the Forgings ~~or Castings~~, as herein described, manufactured

Messrs: A/B. Lindholmen-Motala of Motala Verkstad

Aux. 80374

the Engines No. being constructed by Messrs: Aktieb. Atlas-Diesel,

Stockholm

"KANLAON"

for the Ship ~~the~~, being built by

Messrs: Hong Kong & Wampoa Dock Co: Ld: of Hong Kong

have been inspected by me as set forth below, and found to be, so far as can

seen, sound and free from defects. These have been despatched to

the ship.

~~the ship~~

Lloyd's

6079

10-31



Stockholm, the 5th Oct. 1931

H. J. Andersson

Aux: CRANK SHAFT.

~~TRUST SHAFT~~

~~INTERMEDIATE SHAFT~~

~~TRUCK SHAFT~~

~~FLY WHEEL SHAFT~~

~~SCREW SHAFT~~

S.M. Steel.

Forged.

Yes.

Forgings As per plan No: HA 305

Rough turned and finished.

Standard
pes.

re inch
m/m

cent

Test

fracture

pected

52.5

38.0

180° good

25/8, 5/10-31

PARTICULARS OF OTHER TESTS APPLIED TO CASTINGS:-

any chargeable) £

To be paid at

brought iron, state whether piled bars or scrap. If of steel, state whether made by the Open Hearth process.

007998-008007-0163