

complete the surveys should be summarised. state clearly the cause of repairs, if any, and, in detail, the nature and extent of examinations and subsequent repairs. Remains on account of



# Lloyd's Register of Shipping,

High Close, Wiltshire Road,  
Wokingham, Berks.

SECTION.

524

31 OCT 1940

H.

To the Surveyor at Tallinn.

Vessel's Name, Steamer "MINNA".

QUESTION.

ANSWER.

I have to acquaint you that to complete the Boiler Survey which became due at the end of April last, and to entitle the vessel to a record of "BS.4,40", the safety valves require to be adjusted under steam, and I shall be glad to learn what arrangements the Owners propose making for this matter to receive attention.

I think it well to add that a proposal to carry out the 2nd Special Survey No.1 some time before the expiration of the Year of Grace, in June next, has been agreed to.

*h.h.*

Date:— 1st March, 1941.

The surveyors to this Society are not permitted to hold any surveys on the vessels belonging to the U.S.S.R. in the ports of U.S.S.R.

As all former Estonian ships are now owned by the U.S.S.R., further surveys on these ships are not possible.

*P. Genef*



© 2020

Lloyd's Register  
Foundation