

1

Sent to Chief Surveyors.....
GB

Received from Chief Surveyors..... 21 APR 1949

VESSEL'S NAME "MARY SWEENEY" REPORT Lon. No. 117353a

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.).

Nature of Survey..... When done.....

This vessel was built in 1.47.

The class is subject to (anchors being submitted to the Statutory Test).

The St. JOHN. N. B. Surveyor forwards a letter from the Owners in which they state that they do not propose to continue the vessel's class with this Society.

IT IS SUBMITTED the vessel's class be withdrawn from the Register Book, and three dots (...) inserted in lieu, indicating withdrawal of class at the Owners' request.

Withdraw class from R.B.

Insert (...) 3.49.



© 2021
20.4.49

Lloyd's Register
Foundation
0002028-002039-0052

Y.M.
on F
d, M

is, &

how
wedg
letter

fo. of.

to if n

th
(on h
e leng

ker.

& War

nd Run

he Register
as classed

For Co Dept.

Please return to
"S" Dept.



© 2021

Lloyd's Register
Foundation