

Do  
be  
"MARY SWEENEY"

"PATRICIA SWEENEY"

It is submitted the Surveyors be informed in reply to their letter of the 12.6.47 that the scantlings of the single bottom in the machinery space requested, are for floors, middle line keelson etc., as detailed on page one of their First Entry Report and not bottom shell thicknesses as furnished in their letter.



© 2021

Lloyd's Register  
Foundation  
14-7-97  
1.c.8

008028-008039-0065

150  
17  
classroom  
St. J. ...



© 2021

Lloyd's Register  
Foundation

