

Steel 4-masted Bk. "MOSHULU" - built 1904 - 3117 tons gross

-----

This vessel, which has never been classed with this Society, has been under survey at Vancouver for classification, and the following fees have been charged :-

	<u>Dollars</u>	<u>Pounds</u>
First Entry	35	7
Special Survey	250	50
Special Survey of masts	<u>15</u>	<u>7</u>
	320	64

In previous similar cases it has been customary to charge a fee of approximately 40% of the amount that would be chargeable for Special Survey during construction of a new vessel of the same tonnage.

On this basis the fee chargeable in this case would be say £93, and it is considered that a higher fee than £64 should have been charged.

It is submitted the Vancouver Surveyor be informed accordingly through Mr. French.



24.8.35

Lloyd's Register  
Foundation

008068-008078-0258

ments of the present Rules and found to be equivalent thereto,

able to be supplied the



For Mr Ward  
 then present  
 Class Committee  
 C.E.B.A.S

account of the same company.

It is evident that the company is not doing well and it is not possible to continue the business at the present time. The company is not doing well and it is not possible to continue the business at the present time.

On this point the committee is of the opinion that the company is not doing well and it is not possible to continue the business at the present time.

Balance	Debit	Credit
350	25	25
25	25	25
25	25	25
25	25	25

Balance of the company is not doing well and it is not possible to continue the business at the present time.

The following is a list of the company's assets and liabilities. The company is not doing well and it is not possible to continue the business at the present time.

The company is not doing well and it is not possible to continue the business at the present time.