

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

1st December, 1924.

Dear Sirs,

I duly received your letter of the 27th ultimo respecting the steamer "BRAVORE", and note that the vessel is at present discharging at Llanelly, and that the Owners intend submitting her to the Special Survey No.2.

With regard to your enquiry, I beg to acquaint you that two shell plates, F.4 and G.3, on the port side forward were reported by the Sunderland Surveyors in April 1923 to be indented and several other plates to be slightly indented, and it was recommended that these plates should be dealt with at the Owners' convenience. No further details are available from the reports in this Office, and I would therefore suggest that you should confer with the local Surveyors as to the work which will require to be carried out at the Special Survey.

I am, Dear Sirs,

Yours faithfully,

Assistant to the Secretary.

Messrs. Arnesen, Christensen & Smith,

45, Mount Stuart Square,

CARDIFF.

© 2021

Lloyd's Register
Foundation

008097-008095-0203